On-site product verification report

Decorative light fitting — prepared for a client in the United Arab Emirates

Engagement	**On-site verification, single visit**	Supplier	**A lighting manufacturer · name withheld**
Location	**Xiaolan, Zhongshan, Guangdong, China**	Factory name	**Withheld at the supplier's request**
Client	**An importer in the United Arab Emirates**	Date of visit	**10 September 2026**
Time on site	**Approx. 30 minutes**	Product	**Decorative light fitting**
Verified on site	**Yes**		

1 · WHAT WE WERE ASKED TO DO

The client had the product manufactured and asked us to attend the factory before shipment to confirm, on the record, what was actually there: that the goods existed, that they were the goods ordered, and that they were complete and packed as specified. The client did not ask us to judge whether the product was good.

The visit was made before the order was released for shipment. What follows is a record of what we saw and photographed on the day.

2 · WHAT WE ESTABLISHED ON SITE

ITEM	FINDING
Address visited	An operating manufacturing and assembly premises. Photographed from the road on arrival.
Nature of operation	A production and assembly site with its own showroom. Goods of the type ordered were present and being worked on.
Business licence	Checked on site. The registered name and address are withheld from this redacted copy.
The ordered product	**Present on site. Photographed complete, and photographed with the fitting lit.**
Component parts	Frame and bracket, and the materials used, photographed separately so the client could compare them against the specification.
Materials on site	Stock materials photographed in the factory.
Packing	**Packing photographed at three stages: the packed unit, the packing fill, and the packing data recorded for the consignment.**
Quantity	Checked against the order and recorded. The figure is withheld from this redacted copy.

3 · EVIDENCE DELIVERED TO THE CLIENT

- Original full-resolution photographs taken on site — the premises, the showroom, the finished piece, frame and bracket detail, materials, and packing
- Video recorded on site showing the finished piece with the fitting lit
- This written report
- The packing data recorded at the factory

4 · SCOPE OF THIS REPORT

This report is information only. It records what we observed on the date of the visit and what we were shown. It is not a valuation, a warranty or an approval.

We did not inspect, test or certify product quality, specification or conformity. We do not grade goods and we do not issue pass or fail. We do not comment on price or commercial terms, and we accept no commission, referral fee or other payment on this engagement from any factory. The commercial decision remains the client's own.